



Dan Walsh
Captain

Toronto Fire Services
Fire Prevention Division
South Command
77 Elizabeth Street
2nd floor
Toronto, ON M5G 1P4

Tel: 416 338-9352
Fax: 416 338-9349

September 27, 2007

Susan Lynn Ehrlich, Deanna Evelyn Hurd and
Arthur David Jones
430 Markham Street
Toronto, ON
M6G 2L2

Re: 430 MARKHAM STREET, Toronto

Dear Sir/Madame,

Please be advised that an inspection was conducted on January 9, 2006 and the above-noted property was deemed to be in compliance with Section 9.5 of the Ontario Fire Code, O. Reg. 388/97 as amended, and City of Toronto By-Law No. 60-1998.

In addition to the Retrofit requirements, the Fire Code requires that checks, inspections and tests of the fire protection systems and equipment installed in this building be carried out at prescribed intervals.

Please note that, in addition to the requirements of the Fire Code, the owner is also responsible for the maintenance of Carbon Monoxide Detectors as required by City of Toronto By-Law No. 60-1998.

If you have any questions, please contact the undersigned at (416) 338-9386.

Yours truly,

A handwritten signature in black ink, appearing to read "Christy Kuz".

Christy Kuz
Inspector
Fire Prevention Division
South Command